

## SANITATION CERTIFICATE

I have inspected the buildings and premises of Bappuji Public School, Elivaly , Kodumpidy P O and certified that

- There is sufficient number of well ventilated classrooms and sufficient area is provided for open and playground.
- There is sufficient number of toilets and urinals kept separate for boys and girls are kept clear
- There is protected water supply including water supply including hot water facility is provided with sufficient number of taps. The school and its premises are kept clean and tidy.

Hence on Public Health point of view the sanitation condition of school is satisfactory.

Place Kadanad

Date 27-05-2023



*B. M. M.*

HEALTH INSPECTOR  
PHC KADANAD